



SANTANA - 09181-35024 - SUPLEMENTO PIÑON ATAQUE 0,4

Suplemento piñon ataque 0.4

SHIM, PINION 0.4

CALE, PIGNON 0.4

Vehículo Código de modelo Modificación Tipo

Samurai/SJ SJ419 SJ419 (MY:99, Santana)

Samurai/SJ SJ419 SJ419D (MY:99, Santana)

Samurai/SJ SJ419 SJ419TD (MY:99, Santana)

Vitara/Sidekick SE416 SE416-2 (Santana) TYPE 2

Samurai/SJ SJ413 SJ413 E-III (Santana)

Vitara/Sidekick SE416 SE416-3 (Santana) TYPE 3

Samurai/SJ SJ413 SJ413 (Santana) (E01)

Vitara/Sidekick SE416 SE416 (Santana) TYPE 1

0

