



SANTANA - 83850-56B00 - TIRA PTA. DEL. L/D

Tira puerta delantera derecha

WEATHERSTRIP, INNER RH

JOINT D'ÉTANCHÉITÉ, INTÉRIEUR DE PORTE

Vehículo Código de modelo ??dificación Carrocería

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1993) 93 MODEL

Vitara/Sidekick SE416 SE416-5 TYPE 5

Vitara/Sidekick SE419 SE419D (Santana)

Vitara/Sidekick SV418 SV418 (MY 1997) 97 MODEL SV418

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1995) 95 MODEL

Vitara/Sidekick SE416 SE416-4 TYPE 4

Vitara/Sidekick SE419 SE419D (MY:96, 5DR Santana) 5DR

Vitara/Sidekick SV418 SV418 (MY 1996) 96 MODEL SV418

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1994) 94 MODEL

Vitara/Sidekick SE416 SE416-3 (5DR) TYPE 3

Vitara/Sidekick SE419 SE419TD (MY:97-98,Santana)

Vitara/Sidekick SE416 SE416 (E24) TYPE 1

Vitara/Sidekick SE416 SE416-2 (E24) TYPE 2

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1998) 98 MODEL SE416

Vitara/Sidekick SE416 SE416 (MY:97-98, Santana)

Vitara/Sidekick SE416 SE416-2 (5DR) TYPE 2

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1997) 97 MODEL SE416

Vitara/Sidekick SE416 SE416 (E03,E28,E33,E60:MY 1996) 96 MODEL SE416

Vitara/Sidekick SE416 SE416 E-III (Santana)

Vitara/Sidekick SE416 SE416 (E03,E33:MY 1992) 92 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1994) 94 MODEL

Vitara/Sidekick SE416 SE416 (MY:~95, Santana)

Vitara/Sidekick SV418 SV418 (MY 1998) 98 MODEL SV418

Vitara/Sidekick SE416 SE416 (E28:MY 1995) 95 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1992) 92 MODEL

Vitara/Sidekick SE416 SE416 (MY:96, 5DR Santana) 5DR

Vitara/Sidekick SE416 SE416-3 (E24) TYPE 3

Vitara/Sidekick SE416 SE416 (E28:MY 1989) 89 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1991) 91 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1993) 93 MODEL

Vitara/Sidekick SE416 SE416 (E28:MY 1990) 90 MODEL
Vitara/Sidekick SE416 SE416 (E03,E33:MY 1989) 89 MODEL
Vitara/Sidekick SE416 SE416 (E03,E33:MY 1990) 90 MODEL
Vitara/Sidekick SE420 SE420 HDI 5DR (Santana) 5DR



