



AMJClassics


SANTANA - 95000-58BB1 - C/A.A.VIT.5P.16V.D.A.MY97

Conjunto Aire Acondicionado

Vehiculo Código de modelo Modificación Tipo

Vitara/Sidekick SE416 SE416-5 TYPE 5

Vitara/Sidekick SE416 SE416-4 TYPE 4



SE416-4 E01 248
AIR CONDITIONER(RHD)