



LAND ROVER - LR016715 - PLACA TUERCA BISAGRA

Placa tuerca bisagra

NUT PLATE M8 FOR REAR SIDE DOOR HINGES

PLAQUE D'ÉCROU M8 POUR CHARNIÈRES DE PORTE LATÉRALE ARRIÈRE

Vehículo motor caja Lado volante

Defender 2007- 2.2L 16V TC I4 DSL 122PS PUMA Caja de cambios manual LHD

Defender 2007- 2.2L 16V TC I4 DSL 122PS PUMA Caja de cambios manual RHD

Defender 2007- 2.2L 16V TC I4 DSL 122PS PUMA Manual de 6 velocidades - MT82 LHD

Defender 2007- 2.2L 16V TC I4 DSL 122PS PUMA Manual de 6 velocidades - MT82 RHD


Defender 2007- 2.4L Duratorq-TDCi HPCR(140PS)-Puma Caja de cambios manual LHD

Defender 2007- 2.4L Duratorq-TDCi HPCR(140PS)-Puma Caja de cambios manual RHD

Defender 2007- 2.4L Duratorq-TDCi HPCR(140PS)-Puma Manual de 6 velocidades - MT82 LHD

Defender 2007- 2.4L Duratorq-TDCi HPCR(140PS)-Puma Manual de 6 velocidades - MT82 RHD





C01.370
01-2011
L8
LN0318C