



AMJClassics

LAND ROVER - 533358 - TAPON ROSCA

Tapon de rosca

OIL FILLER PLUG GEARBOX

BOUCHON DE REMPLISSAGE D'HUILE

Compatibilidad

Series 1 Series 3 Series 2 101 Forward Control Range Rover Classic Defender

Land Rover 6C Gasolina



Exploded view diagram of a reinforced gear box assembly. The diagram shows the main housing (1) and various internal and external components, including gears (13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59), shafts (6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59), and mounting brackets (5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59). The assembly is shown in a disassembled state to illustrate the relationship between the parts. A red box highlights part 28.

CAJA CAMBIOS REFORZADA
GEAR BOX REINFORCED
BOITE DE VITESSES RENFORCEE

